

INTERIM LETTER OF AUTHORIZATION

NR. 25050



This is to certify that⁽¹⁾ ⁽²⁾

Petercem in Frontonas in France

is hereby authorized⁽¹⁾ to act as

Manufacturer

in accordance with the applicable rules of

10 CFR50 Appendix B

This authorization is granted on the basis of their Quality Manual ref. PTM24Q372 indice I (08/08/2024), which scope and implementation have been reviewed and conditionally accepted by Tractebel on June 10th to 12nd, 2025 (see audit report ref. CNT-KCD/4FR/0032366/000/00 and Type-Test report ref. CNT-KCD/4FR/0032366/001/00)

For the design, procurement, manufacturing, examination, testing, storage, handling, shipping and packaging of

Limit switches types :

- F 6334/35 (obsolete) 1EA/LT (RSQ 15.00)
- F 6336/37 (obsolete) 1EA/LT (RSQ 15.00)
- F 6387/88 1EB/irrad. 3 Mrad (RSQ 15.01)
- F 6613/14 1EA/LT (RSQ 15.02)
- F 20/21 LG 2 – RSB R8 1EA/LT (RSQ 15.03)
- F 20/21 LG 1 – RSB R8 1EA/LT (RSQ 15.04)
- F 6389/90 1EA/CT (RSQ 15.05)
- F 7082/83 1EA/CT (RSQ 15.06)
- F 7093/94 1EA/LT (RSQ 15.07)
- F 7195/96 1EB/without irrad. (RSQ 15.08)
- F 7191/92 1EA/LT (RSQ 15.09)
- F 6332/33-1 1EB/without irrad. 10 Mrad (RSQ 84.06)

Micro switches types :

- R6354-1 1EA/TCT (RSQ 15.00)
- R6380-1 1EA/TCT (RSQ 15.00)
- R6433-1 1EA/TCT (RSQ 15.00)
- R6469-1 1EA/TCT (RSQ 15.00)

at the above location only, from June 13rd, 2025 until June 11st, 2027

This authorization is subject to the holder's agreement to achieve the implementation of his Quality Assurance program and to have it reviewed and accepted by Tractebel prior to the expiration date of his Interim Letter, and prior to the issuance of a Certificate of Authorization

Henrotte Philippe
Chef de Section Qualité&Repair (MQR)
Maintenance Tihange

Martens Dirk
Afdelingshoofd Program Engineering
Program Engineering Doel

(1) This authorization does not relieve its holder from his contractual obligations towards the owner. By this authorization, Electrabel does not "approve", "certify", "rate", or "endorse" any product or construction.

(2) In case of any change to the scope, performance address, company name, or any change in company organization or shareholding; the authorization document is deemed to be obsolete and will need renewal.